

WARNING



- Disconnect from electric supply before servicing.
- Replace all panels before operating.


SWITCH	TIMER CYCLE SCHEDULE IN MINUTES					
	TIMED	OFF	AIR	OFF	PERM. PRESS	OFF
TM-WB						
TM-OR						
BK-BU-V						
BK-BU	85		35		92	
BK-R		10				
T-W					40	
T-BY					+++	

+ = CLOSED APPROX. 15 SECONDS EVERY 5 MINUTES




MANUFACTURED UNDER ONE
OR MORE OF THE
FOLLOWING U.S. PATENTS:

3,702,030	3,962,617
3,762,064	4,086,709
3,769,716	4,132,008
3,815,258	4,385,452
3,889,392	4,430,809
3,890,720	4,003,613
3,959,891	4,821,535

LI LINE - BLACK



LABEL NO.
3398043REV. REL.



DIAGRAM

GAS

